



ALLEN DATAGRAPH

Technical Support Bulletin: Work Around for CAD bug


September 15, 2004

Abstract: PowerCAD and MonumentCAD have trouble with extremely long paths. The cad program only output a small portion of the path to the printer driver. This TSB shows a work around.

Some of the premade artwork in MonumentCAD has a long scalloped paths around the whole monument. While there is no known limit to the length of a path or the number of point in Windows or the printer driver it appears as if only a portion of the long path is sent to the printer driver. This file fails, as the outside border is very long. Only a portion of the file is output to the driver. Splitting the path with the “Modify -> Break” tool into smaller pieces allows the Cad program to send the pieces correctly.



Before breaking path



After breaking path